

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L4	619	((vent ventilation duct conduit passageway pipe outlet inlet) with differential with pressure with (fault error defect fail\$4 inaccurat\$4 miscalculat\$4 flaw fallacy))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/30 12:43
L5	1123104	engine	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/30 12:43
L6	417009	"73"/\$.ccls. "123"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/30 12:43
L7	26	4 & 5 & 6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/07/30 12:44